

END OF LIFE NOTIFICATION

Title Discontinuance of the 1.8 Volt LVDS Series Oscillators.

Article: **Products Affected:** Pletronics **LV77XXDX, LV77XXDCX, LV77XXDEX, LV11XXBX, LV11XXBCX & LV11XXBEX.**

LV77



Reason: Obsolete IC

Recommended replacement: No recommended replacement available for 1.8 volt option. Suggested to change voltage to 2.5 volts or 3.3 volts operation.

Last Purchase Date: Due to discontinuance of IC, no last time purchase is available.

Date Created 8/14/12

Created By Pletronics Engineering
Ple-eng-mfg@pletronics.com